




General Care:


-Keep your furniture out direct sunlight-Use desk pads and coasters to protect the surface from dents,scratches,and moisture from hot or cold liquids.








Cleaning:

-For cleaning, wipe the surface with a damp (not wet) cloth or wipe dry with a clean lint free cotton cloth.
-Window cleaning liquid or a similar cleaning liquid can be used to clean glass surface.










■ PARTS LIST



1  X4	2  X1	3  X4	
4  X4	5  X2	6  X1	7  X2
8  X1	9  X1	10  X1	11  X1



12  X1	13  X1		
14  X1	15  X1		
16  X1	17  X1	18  X1	
19  X1	20  X1	21  X1	22  X1
23  X1	24  X1		





SCREWS LIST


PART	QTY.	ITEM	
A	12	6X40 MM	
B	14	6X12 MM	
C	6	6X25 MM	
D	8	6X40 MM	
E	2	4X10 MM	
F	12	5X40 MM	
G	8	3X12 MM	
H	6	3X15 MM	

PART	QTY.	ITEM	
I	4	4X35 MM	
J	12	5X45 MM	
K	3	6X25 MM	
L	12	Φ 15 MM	
M	3	Φ 12 MM	
N	16	8X30 MM	
	1		


6X40MM & 6X25MM BOLT INSTALLATION AS BELOW:



A1.




Rotate connecting piece if found
in position illustrated above




Correct orientation to
receive bolts


A2.



A3.



A4.



ASSEMBLY STEPS:

1

1 X4

Don't Tighten Screws

■ SCREWS
D 6X40 MM
x4

2

2

1 X4

Tighten All Screws

■ SCREWS
B 6X12 MM
x4

3

3 X4

1 X4


2

4 X4

Tighten All Screws

■ SCREWS
B 6X12 MM
x8

4




■ SCREWS

L Φ 15 MM
x2

■ SCREWS

A 6X40 MM
x2

5




■ SCREWS

A 6X40 MM
x10

L Φ 15 MM
x10

N 8X30 MM
x8


6



■ SCREWS

H 3X15 MM
x2

7




■ SCREWS

H 3X15 MM

x4



8



■ SCREWS

F 5X40 MM


x12

N 8X30 MM

x8



9





■ SCREWS

D 6X40 MM

x4



10



■ SCREWS


K 6X25 MM

x3

M Φ 12 MM

x3

11





■ SCREWS

J 5X45 MM

x6

12




■ SCREWS

J 5X45 MM

x6

13




■ SCREWS

E 4X10 MM

x2



14




■ SCREWS

C 6X25 MM

x2



15




■ SCREWS

C 6X25 MM

 x4



16




■ SCREWS

G 3X12 MM

 x4



17




■ SCREWS

I 4X35 MM


 x4



18



19




■ SCREWS

B 6X12 MM

x2



20



■ SCREWS

G 3X12 MM

x4



